
FLUID POWER Design Data Sheet-



Revised Sheet 3 - Womack Design Data File



ELECTRIC MOTOR SIZE FOR HYDRAULIC PUMP DRIVE

Figures in the body of this table show the horsepower needed to drive a positive displacement hydraulic pump, and would be valid either for electric motor or engine drive. The table was calculated from the formula: HP = PSI x GPM \div (1714 x 0.85), assuming a pump efficiency of 85%, which would be representative of most positive displacement pumps. For pumps with other than 85% efficiency, substitute the actual efficiency, in decimals, in place of 0.85 in the formula.

For values of PSI and GPM not shown, calculations can be made with the above formula, or values can be interpolated from the table.

GPM	500 PSI	750 PSI	1000 PSI	1250 PSI	1500 PSI	1750 PSI	2000 PSI	2500 PSI	3000 PSI	3500 PSI	4000 PSI	5000 PSI	6000 PSI
3	1.03	1.54	2.06	2.57	3.09	3.60	4.12	5.15	6.18	7.21	8.24	10.3	12.4
5	1.72	2.57	3.43	4.29	5.15	6.00	6.86	8.58	10.3	12.0	13.7	17.2	20.6
7½	2.57	3.86	5.15	6.43	7.72	9.01	10.3	12.9	15.4	18.0	20.6	25.7	30.9
10	3.43	5.15	6.86	8.58	10.3	12.0	13.7	17.2	20.6	24.0	27.5	34.3	41.2
12½	4.29	6.43	8.58	10.7	12.9	15.0	17.2	21.4	25.7	30.0	34.3	42.9	51.5
15	5.15	7.72	10.3	12.9	15.4	18.0	20.6	25.7	30.9	36.0	41.2	51.5	61.8
17½	6.01	9.01	12.0	15.0	18.0	21.0	24.0	30.0	36.0	42.0	48.0	60.1	72.1
20	6.86	10.3	13.7	17.2	20.6	24.0	27.5	34.3	41.2	48.0	54.9	68.6	82.4
221/2	7.72	11.6	15.4	19.3	23.2	27.0	30.9	38.6	46.3	54.1	61.8	77.2	92.7
25	8.58	12.9	17.2	21.4	25.7	30.0	34.3	42.9	51.5	60.1	68.6	85.8	103
30	10.3	15.4	20.6	25.7	30.9	36.0	41.2	51.5	61.8	72.1	82.4	103	124
35	12.0	18.0	24.0	30.0	36.0	42.0	48.0	60.1	72.1	84.1	96.1	120	144
40	13.7	20.6	27.5	34.3	41.2	48.0	54.9	68.6	82.4	96.1	110	137	165
45	15.4	23.2	30.9	38.6	46.3	54.1	61.8	77.2	92.7	108	124	154	185
50	17.2	25.7	34.3	42.9	51.5	60.1	68.6	85.8	103	120	137	172	206
55	18.9	28.3	37.8	47.2	56.6	66.1	75.5	94.4	113	132	151	189	227
60	20.6	30.9	41.2	51.5	61.8	72.1	82.4	103	124	144	165	206	247
65	22.3	33.5	44.6	55.8	66.9	78.1	89.2	112	134	156	178	223	268
70	24.0	36.0	48.0	60.1	72.1	84.1	96.1	120	144	168	192	240	288
75	25.7	38.6	51.5	64.3	77.2	90.1	103	129	154	180	206	257	309
80	27.5	41.2	54.9	68.7	82.4	96.1	110	137	165	192	220	275	329
85	29.2	43.8	58.3	72.9	87.5	102	117	146	175	204	233	292	350
90	30.9	46.3	61.8	77.2	92.7	108	124	154	185	216	247	309	371
100	34.3	51.5	68.6	85.8	103	120	137	172	206	240	275	343	412

USING THE TABLE

Pressure and flow ranges in the table will cover most applications, but intermediate values can be estimated by combining values in the table. Example: HP required at 4500 PSI is the sum of values shown in the 2000 and 2500 PSI columns. At 73 GPM, for example, HP will be the sum of values in the 3 and 70 GPM lines. At 10,000 PSI, power is twice the value at 5000 PSI at the same GPM.

For pressures less than 500 PSI, HP calculations tend to become inaccurate because mechanical friction and fluid flow losses are a greater percentage of applied pressure. Approximate power requirements can be estimated with

the "Rule of 1500" which states:

1 HP is required for each 1 GPM at 1500 PSI or any multiple of 1500 such as 3 GPM at 500 PSI, 2 GPM at 750 PSI, 1/2 GPM at 3000 PSI. etc.

Another handy rule-of-thumb is that it takes about 5% of the pump maximum rated HP to drive the pump when unloaded and pressure is very low. This power is consumed in bearing losses and fluid flow losses.

PERMISSIBLE OVERLOADING OF A MOTOR

factors on most open frame sizes is 0.15 which means that the motor can be overloaded about 15% above current

The motor most often used to drive a hydraulic pump is a 3-phase, induction-type, Design B motor. The service

shown on its nameplate, assuming it is being operated in a normal temperature environment. TEFC and explosion proof motors have a service factor of 1.0.

An electric motor can be overloaded for short periods during the cycle provided the average horsepower is no greater than its nameplate rating plus service factor where this applies.

The amount of intermittent overloading is up to the user, but we suggest the overload be no more than 25% above its nameplate current rating sustained no longer than about 10% of the time required for a complete cycle.

OPERATION ON INCORRECT FREQUENCY (Hz)

Most A-C 60 Hz motors can be operated on a 50 Hz line and vice versa, but adjustments will have to be made in the current, HP, and speed ratings. The important thing to remember is that it is the current which causes heating. The HP which can be produced will be related to its current draw, and may be more or less than its nameplate rating.

Characteristic	60 HZ Motor on 50 Hz Line	50 Hz Motor on 60 Hz Line
HP will be: Adjust voltage to:* Full load torque: Breakdown torque: Locked rotor torque: Locked rotor current: Speed, RPM: Max. service factor: Noise level:	16-2/3 less 16-2/3 less Same Same Same 5% less 16-2/3 less	20% more 20% more Same Same Same 6% more 20% more 1.00 More
MODE TEVEL:	Less	MOLE

*Voltage adjustment is to maintain current at rated value, to produce rated shaft torque. Current is always a limiting factor on a variation in rated Hz (frequency) or voltage.

EFFECTS OF LOW VOLTAGE

Nameplate HP is based on full voltage being available. HP output is a combination of voltage times current. If voltage is too low, then to produce rated HP the current must be too high, and this overheats the motor. Motors can usually accommodate as low as 90% of rated voltage and still produce nameplate HP although temperature rise in the windings will be greater than rated rise. For permanent operation on a voltage source known to be low, the HP load should be limited, and reduced by the same percentage that the voltage is low.

EFFECTS OF HIGH VOLTAGE

If motor load does not exceed nameplate HP rating, full load current will be lower than nameplate rating and the motor will run cooler than rating. However, its starting and breakdown current (at stall) will be higher than normal. The wiring, fusing, and thermal overload protection will have to be sized accordingly. Motor noise will increase.

USING AN OVERSIZE MOTOR

Using a 20 HP motor on a system which requires only 10 HP, for example, will give good results for running the pump but will consume more electricity than a 10 HP motor and will cause the power factor of the plant electric system to be poorer, especially during periods the motor is idling. Idling current of a 20 HP motor is about half the full load current of a 10 HP motor. This is an extra power waste during periods in the cycle when the pump is idling.

USING AN UNDERSIZE MOTOR

Using a 20 HP motor on a system which requires 25 HP for brief periods is quite possible, but during overload

periods the current of such a motor may be about twice the current of a 25 HP motor. There will be an extra waste of power during peak periods in the cycle. But the smaller motor could more than make this up during periods in the cycle when less than 20 HP is required.

Some power companies charge for power by the number of kilowatt-hours used. But they may base their rate on the maximum current flow at any moment during the metering period. A poorer power factor in the plant increases current flow without increasing HP delivered. Therefore, either oversizing or undersizing a pump-drive electric motor will increase the cost of running the system.

NEMA Standard Terminal Markings and Connections for 9-Lead, 3-Phase Motors


These diagrams show which motor leads must be wired together inside the motor junction box for operation of the motor on its highest or lowest voltage as stated on its nameplate. Normally, on a star connected motor the center point of the windings is brought out for connection to ground.

DELTA CONNECTION

				Together
Low	1&6&7	2&4&8	3&5&9	None
High	1	2	3	4 & 7, 5 & 8, 6 & 9

STAR (WYE) CONNECTION

Voltage	Line 1	Line 2	Line 3	Together	
Low	1 & 7	2 & 8	3 & 9	4 & 5 & 6	
High	1	2	3	4 & 7. 5 & 8. 6 &	9



Published by:

WOMACK EDUCATIONAL PUBLICATIONS

Department of Womack Machine Supply Co. 13835 Senlac Dr. Farmers Branch, TX 75234 Tel: 1-800-569-9801 Fax: (214) 630-5314 www.womack-educational.com

@1988 by Womack Machine Supply Co. All rights reserved. Illegal to reproduce any part of this sheet without permission. Printed in U.S.A. This company assumes no liability for errors in data nor in safe and/or satisfactory operation of equipment designed from this information.